


**Pipe Graphic Report of PLR**      MH 1      X      for CUMMUINTY HOA


<b>Work Order</b>	<b>Contract</b>		<b>Video</b>		<b>Setup</b>		1		
<b>Facility</b>	<b>Operator</b>	TROY	<b>Van Ref</b>		<b>Surveyed On</b>	02/01/2022			
<b>Street Name</b>	WAPITI LOOP		<b>City</b>	HYRUM					
<b>Location type</b>									
<b>Surface</b>									
<b>Survey purpose</b>	Random survey of pipes and things		<b>Weather</b>		Snow				
<b>Pipe Use</b>	Sanitary		<b>Schedule length</b>	230.3	Ft	<b>From</b>	MH 2	<b>Depth</b>	F f t
<b>Shape</b>	Circular		<b>Size</b>	8	by	ins	<b>To</b>	MH 1	
<b>Material</b>	Polyvinyl chloride		<b>Joint spacing</b>		Ft		<b>Direction</b>	Upstream	
<b>Lining</b>			<b>Year laid</b>				<b>Pre-clean</b>	Y	
							<b>Last cleaned</b>	2/1/2022	
<b>General note</b>						Structural	Service	Constructional	
<b>Location note</b>						Miscellaneous	Hydraulic		



**PipeLogix Inc.**  
**Phone: 866-299-3150**  
**Fax: 760-406-6023**

**Pipe Graphic Report of PLR**      MH 2      X      for CUMMUINTY HOA


<b>Work Order</b>	<b>Contract</b>		<b>Video</b>		<b>Setup</b>	2		
<b>Facility</b>	<b>Operator</b>	TROY	<b>Van Ref</b>	<b>Surveyed On</b>	02/01/2022			
<b>Street Name</b>	WAPITI LOOP		<b>City</b>	HYRUM				
<b>Location type</b>								
<b>Surface</b>								
<b>Survey purpose</b>	Random survey of pipes and things		<b>Weather</b>	Snow				
<b>Pipe Use</b>	Sanitary	<b>Schedule length</b>	183.6 Ft	<b>From</b>	MH 2	<b>Depth</b>	F t	
<b>Shape</b>	Circular	<b>Size</b>	8 by	<b>To</b>	MH 3	<b>Depth</b>		
<b>Material</b>	Polyvinyl chloride	<b>Joint spacing</b>	Ft	<b>Direction</b>	Downstream			
<b>Lining</b>			<b>Year laid</b>	<b>Pre-clean</b>	Y	<b>Last cleaned</b>		2/1/2022
<b>General note</b>					<b>Structural</b>	<b>Service</b>		<b>Constructional</b>
<b>Location note</b>					<b>Miscellaneous</b>	<b>Hydraulic</b>		



**PipeLogix Inc.**  
**Phone: 866-299-3150**  
**Fax: 760-406-6023**

**Pipe Graphic Report of PLR**      MH 3      X      for CUMMUINTY HOA


<b>Work Order</b>	<b>Contract</b>		<b>Video</b>		<b>Setup</b>	3			
<b>Facility</b>	<b>Operator</b>	TROY	<b>Van Ref</b>		<b>Surveyed On</b>	02/01/2022			
<b>Street Name</b>	WAPITI LOOP		<b>City</b>	HYRUM					
<b>Location type</b>									
<b>Surface</b>									
<b>Survey purpose</b>	Random survey of pipes and things		<b>Weather</b>		Snow				
<b>Pipe Use</b>	Sanitary	<b>Schedule length</b>	74.4	Ft	<b>From</b>	MH 3	<b>Depth</b>	F f t	
<b>Shape</b>	Circular	<b>Size</b>	8	by	ins	<b>To</b>	MH 4		<b>Depth</b>
<b>Material</b>	Polyvinyl chloride	<b>Joint spacing</b>			Ft	<b>Direction</b>	Downstream		
<b>Lining</b>			<b>Year laid</b>			<b>Pre-clean</b>	Y		<b>Last cleaned</b>
<b>General note</b>					<b>Structural</b>	<b>Service</b>	<b>Constructional</b>		
<b>Location note</b>					<b>Miscellaneous</b>	<b>Hydraulic</b>			



**PipeLogix Inc.**  
**Phone: 866-299-3150**  
**Fax: 760-406-6023**

**Pipe Graphic Report of PLR**      MH 4      X      for CUMMUINTY HOA


<b>Work Order</b>	<b>Contract</b>		<b>Video</b>		<b>Setup</b>		4		
<b>Facility</b>	<b>Operator</b>	TROY	<b>Van Ref</b>		<b>Surveyed On</b>	02/01/2022			
<b>Street Name</b>	WAPITI LOOP		<b>City</b>	HYRUM					
<b>Location type</b>									
<b>Surface</b>									
<b>Survey purpose</b>	Random survey of pipes and things		<b>Weather</b>		Snow				
<b>Pipe Use</b>	Sanitary		<b>Schedule length</b>	73.3	Ft	<b>From</b>	MH 4	<b>Depth</b>	F f t
<b>Shape</b>	Circular		<b>Size</b>	8	by	ins	<b>To</b>	MH 5	
<b>Material</b>	Polyvinyl chloride		<b>Joint spacing</b>		Ft	<b>Direction</b>		Downstream	
<b>Lining</b>			<b>Year laid</b>			<b>Pre-clean</b>	Y	<b>Last cleaned</b>	
<b>General note</b>						Structural	Service	Constructional	
<b>Location note</b>						Miscellaneous	Hydraulic		



**PipeLogix Inc.**  
**Phone: 866-299-3150**  
**Fax: 760-406-6023**

**Pipe Graphic Report of PLR**      MH 5      X      for CUMMUINTY HOA


<b>Work Order</b>	<b>Contract</b>		<b>Video</b>		<b>Setup</b>	5
<b>Facility</b>	<b>Operator</b>	TROY	<b>Van Ref</b>	<b>Surveyed On</b>	02/01/2022	
<b>Street Name</b>	WAPITI LOOP		<b>City</b>	HYRUM		
<b>Location type</b>						
<b>Surface</b>						
<b>Survey purpose</b>	Random survey of pipes and things		<b>Weather</b>	Snow		
<b>Pipe Use</b>	Sanitary	<b>Schedule length</b>	132.7 Ft	<b>From</b>	MH 5	<b>Depth</b>
<b>Shape</b>	Circular	<b>Size</b>	8 by ins	<b>To</b>	MH 6	<b>Depth</b>
<b>Material</b>	Polyvinyl chloride	<b>Joint spacing</b>	Ft	<b>Direction</b>	Downstream	
<b>Lining</b>			<b>Year laid</b>	<b>Pre-clean</b>	Y	<b>Last cleaned</b>
<b>General note</b>				Structural	Service	Constructional
<b>Location note</b>				Miscellaneous	Hydraulic	



**PipeLogix Inc.**  
**Phone: 866-299-3150**  
**Fax: 760-406-6023**

**Pipe Graphic Report of PLR**      MH 7      X      for CUMMUINTY HOA


<b>Work Order</b>	<b>Contract</b>		<b>Video</b>		<b>Setup</b>	7				
<b>Facility</b>	<b>Operator</b>	TROY	<b>Van Ref</b>	<b>Surveyed On</b>	02/01/2022					
<b>Street Name</b>	TULE DRIVE		<b>City</b>	HYRUM						
<b>Location type</b>										
<b>Surface</b>										
<b>Survey purpose</b>	Random survey of pipes and things		<b>Weather</b>	Snow						
<b>Pipe Use</b>	Sanitary	<b>Schedule length</b>	302.1	Ft	<b>From</b>	MH 7	<b>Depth</b>	F f t		
<b>Shape</b>	Circular	<b>Size</b>	8	by	ins	<b>To</b>	MH 6		<b>Depth</b>	
<b>Material</b>	Polyvinyl chloride	<b>Joint spacing</b>			Ft	<b>Direction</b>	Downstream			
<b>Lining</b>			<b>Year laid</b>			<b>Pre-clean</b>	Y		<b>Last cleaned</b>	2/1/2022
<b>General note</b>					<b>Structural</b>	<b>Service</b>	<b>Constructional</b>			
<b>Location note</b>					<b>Miscellaneous</b>	<b>Hydraulic</b>				



**PipeLogix Inc.**  
**Phone: 866-299-3150**  
**Fax: 760-406-6023**

**Pipe Graphic Report of PLR**      MH 8      X      for CUMMUINTY HOA


<b>Work Order</b>	<b>Contract</b>		<b>Video</b>		<b>Setup</b>	6
<b>Facility</b>	<b>Operator</b>	TROY	<b>Van Ref</b>	<b>Surveyed On</b>	02/01/2022	
<b>Street Name</b>	TULE DRIVE		<b>City</b>	HYRUM		
<b>Location type</b>						
<b>Surface</b>						
<b>Survey purpose</b>	Random survey of pipes and things		<b>Weather</b>	Snow		
<b>Pipe Use</b>	Sanitary	<b>Schedule length</b>	152.8 Ft	<b>From</b>	MH 8	<b>Depth</b>
<b>Shape</b>	Circular	<b>Size</b>	8 by ins	<b>To</b>	MH 7	<b>Depth</b>
<b>Material</b>	Polyvinyl chloride	<b>Joint spacing</b>	Ft	<b>Direction</b>	Downstream	
<b>Lining</b>			<b>Year laid</b>	<b>Pre-clean</b>	Y	<b>Last cleaned</b>
<b>General note</b>				Structural	Service	Constructional
<b>Location note</b>				Miscellaneous	Hydraulic	



**PipeLogix Inc.**  
**Phone: 866-299-3150**  
**Fax: 760-406-6023**

**Pipe Graphic Report of PLR**      MH 6      X      for CUMMUINTY HOA

<b>Work Order</b>	<b>Contract</b>		<b>Video</b>		<b>Setup</b>	8	
<b>Facility</b>	<b>Operator</b>	TROY	<b>Van Ref</b>		<b>Surveyed On</b>	02/03/2022	
<b>Street Name</b>	WAPITI LP & ROCKY MTN WAY		<b>City</b>	HYRUM			
<b>Location type</b>							
<b>Surface</b>							
<b>Survey purpose</b>	Random survey of pipes and things		<b>Weather</b>		Snow		
<b>Pipe Use</b>	Sanitary	<b>Schedule length</b>	397.7	Ft	<b>From</b>	MH 9	
<b>Shape</b>	Circular	<b>Size</b>	8	by	ins	<b>To</b>	MH 6
<b>Material</b>	Polyvinyl chloride	<b>Joint spacing</b>			Ft	<b>Direction</b>	Upstream
<b>Lining</b>			<b>Year laid</b>			<b>Pre-clean</b>	Y
					<b>Last cleaned</b>	2/1/2022	
<b>General note</b>					Structural	Service	Constructional
<b>Location note</b>					Miscellaneous	Hydraulic	




**PipeLogix Inc.**  
**Phone: 866-299-3150**  
**Fax: 760-406-6023**



**Pipe Graphic Report of PLR**      MH 10      X      for CUMMUINTY HOA


<b>Work Order</b>	<b>Contract</b>		<b>Video</b>		<b>Setup</b>	9
<b>Facility</b>	<b>Operator</b>	TROY	<b>Van Ref</b>	<b>Surveyed On</b>	02/03/2022	
<b>Street Name</b>	WAPITI LP & ROCKY MTN WAY		<b>City</b>	HYRUM		
<b>Location type</b>						
<b>Surface</b>						
<b>Survey purpose</b>	Random survey of pipes and things		<b>Weather</b>	Snow		
<b>Pipe Use</b>	Sanitary	<b>Schedule length</b>	156.2 Ft	<b>From</b>	MH 9	<b>Depth</b>
<b>Shape</b>	Circular	<b>Size</b>	8 by ins	<b>To</b>	MH 10	<b>Depth</b>
<b>Material</b>	Polyvinyl chloride	<b>Joint spacing</b>	Ft	<b>Direction</b>	Upstream	
<b>Lining</b>			<b>Year laid</b>	<b>Pre-clean</b>	Y	<b>Last cleaned</b>
<b>General note</b>				Structural	Service	Constructional
<b>Location note</b>				Miscellaneous	Hydraulic	



**PipeLogix Inc.**  
**Phone: 866-299-3150**  
**Fax: 760-406-6023**


**Pipe Graphic Report of PLR**      MH 11      X      for CUMMUINTY HOA

<b>Work Order</b>	<b>Contract</b>		<b>Video</b>		<b>Setup</b>	10
<b>Facility</b>	<b>Operator</b>	TROY	<b>Van Ref</b>		<b>Surveyed On</b>	02/03/2022
<b>Street Name</b>	WAPITI LP & ROCKY MTN WAY		<b>City</b>	HYRUM		
<b>Location type</b>						
<b>Surface</b>						
<b>Survey purpose</b>	Random survey of pipes and things		<b>Weather</b>		Snow	
<b>Pipe Use</b>	Sanitary	<b>Schedule length</b>	352.0	Ft	<b>From</b>	MH 10
<b>Shape</b>	Circular	<b>Size</b>	8	by	<b>To</b>	MH 11
<b>Material</b>	Polyvinyl chloride	<b>Joint spacing</b>			<b>Direction</b>	Upstream
<b>Lining</b>			<b>Year laid</b>			<b>Pre-clean</b> Y <b>Last cleaned</b> 2/1/2022
<b>General note</b>					<b>Structural</b>	<b>Service</b>
<b>Location note</b>					<b>Miscellaneous</b>	<b>Hydraulic</b>
					<b>Constructional</b>	



**Pipe Graphic Report of PLR**      MH 11      A      for CUMMUINTY HOA


<b>Work Order</b>	<b>Contract</b>		<b>Video</b>		<b>Setup</b>	19
<b>Facility</b>	<b>Operator</b>	TROY	<b>Van Ref</b>	<b>Surveyed On</b>	02/04/2022	
<b>Street Name</b>	30 S & MAMITOBAN LN		<b>City</b>	HYRUM		
<b>Location type</b>						
<b>Surface</b>						
<b>Survey purpose</b>	Random survey of pipes and things		<b>Weather</b>	Snow		
<b>Pipe Use</b>	Sanitary	<b>Schedule length</b>	231.7 Ft	<b>From</b>	MH 11	<b>Depth</b>
<b>Shape</b>	Circular	<b>Size</b>	8 by ins	<b>To</b>	EXIST MH	<b>Depth</b>
<b>Material</b>	Polyvinyl chloride	<b>Joint spacing</b>	Ft	<b>Direction</b>	Downstream	
<b>Lining</b>			<b>Year laid</b>	<b>Pre-clean</b>	Y	<b>Last cleaned</b>
<b>General note</b>				Structural	Service	Constructional
<b>Location note</b>				Miscellaneous	Hydraulic	



**PipeLogix Inc.**  
**Phone: 866-299-3150**  
**Fax: 760-406-6023**

**Pipe Graphic Report of PLR**      MH 9      X      for CUMMUINTY HOA


<b>Work Order</b>	<b>Contract</b>		<b>Video</b>		<b>Setup</b>	18
<b>Facility</b>	<b>Operator</b>	TROY	<b>Van Ref</b>	<b>Surveyed On</b>	02/04/2022	
<b>Street Name</b>	30 S & MAMITOBAN LN		<b>City</b>	HYRUM		
<b>Location type</b>						
<b>Surface</b>						
<b>Survey purpose</b>	Random survey of pipes and things		<b>Weather</b>	Snow		
<b>Pipe Use</b>	Sanitary	<b>Schedule length</b>	110.9 Ft	<b>From</b>	MH 11	<b>Depth</b>
<b>Shape</b>	Circular	<b>Size</b>	8 by ins	<b>To</b>	MH 9	<b>Depth</b>
<b>Material</b>	Polyvinyl chloride	<b>Joint spacing</b>	Ft	<b>Direction</b>	Upstream	
<b>Lining</b>			<b>Year laid</b>	<b>Pre-clean</b>	Y	<b>Last cleaned</b>
<b>General note</b>				Structural	Service	Constructional
<b>Location note</b>				Miscellaneous	Hydraulic	



**PipeLogix Inc.**  
**Phone: 866-299-3150**  
**Fax: 760-406-6023**

**Pipe Graphic Report of PLR**      MH 12      X      for CUMMUINTY HOA


<b>Work Order</b>	<b>Contract</b>		<b>Video</b>		<b>Setup</b>	17				
<b>Facility</b>	<b>Operator</b>	TROY	<b>Van Ref</b>		<b>Surveyed On</b>	02/04/2022				
<b>Street Name</b>	30 S & MAMITOBAN LN		<b>City</b>	HYRUM						
<b>Location type</b>										
<b>Surface</b>										
<b>Survey purpose</b>	Random survey of pipes and things		<b>Weather</b>	Snow						
<b>Pipe Use</b>	Sanitary	<b>Schedule length</b>	147.4	Ft	<b>From</b>	MH 11	<b>Depth</b>	F t		
<b>Shape</b>	Circular	<b>Size</b>	8	by	ins	<b>To</b>	MH 12		<b>Depth</b>	
<b>Material</b>	Polyvinyl chloride	<b>Joint spacing</b>			Ft	<b>Direction</b>	Upstream			
<b>Lining</b>			<b>Year laid</b>			<b>Pre-clean</b>	Y		<b>Last cleaned</b>	2/1/2022
<b>General note</b>					<b>Structural</b>	<b>Service</b>	<b>Constructional</b>			
<b>Location note</b>					<b>Miscellaneous</b>	<b>Hydraulic</b>				



**PipeLogix Inc.**  
**Phone: 866-299-3150**  
**Fax: 760-406-6023**

**Pipe Graphic Report of PLR**      MH 13      X      for CUMMUINTY HOA


<b>Work Order</b>	<b>Contract</b>		<b>Video</b>		<b>Setup</b>	16
<b>Facility</b>	<b>Operator</b>	TROY	<b>Van Ref</b>		<b>Surveyed On</b>	02/03/2022
<b>Street Name</b>	WAPITI LP & MAMITOBAN LN		<b>City</b>	HYRUM		
<b>Location type</b>						
<b>Surface</b>						
<b>Survey purpose</b>	Random survey of pipes and things		<b>Weather</b>		Snow	
<b>Pipe Use</b>	Sanitary	<b>Schedule length</b>	259.4	Ft	<b>From</b>	MH 13
<b>Shape</b>	Circular	<b>Size</b>	8	by	<b>To</b>	MH 12
<b>Material</b>	Polyvinyl chloride	<b>Joint spacing</b>			<b>Direction</b>	Downstream
<b>Lining</b>			<b>Year laid</b>			<b>Pre-clean</b> Y <b>Last cleaned</b> 2/1/2022
<b>General note</b>					<b>Structural</b>	<b>Service</b>
<b>Location note</b>					<b>Miscellaneous</b>	<b>Hydraulic</b>



**PipeLogix Inc.**  
**Phone: 866-299-3150**  
**Fax: 760-406-6023**

**Pipe Graphic Report of PLR**      MH 14      X      for CUMMUINTY HOA


<b>Work Order</b>	<b>Contract</b>		<b>Video</b>		<b>Setup</b>	15
<b>Facility</b>	<b>Operator</b>	TROY	<b>Van Ref</b>		<b>Surveyed On</b>	02/03/2022
<b>Street Name</b>	WAPITI LP & MAMITOBAN LN		<b>City</b>	HYRUM		
<b>Location type</b>						
<b>Surface</b>						
<b>Survey purpose</b>	Random survey of pipes and things		<b>Weather</b>		Snow	
<b>Pipe Use</b>	Sanitary	<b>Schedule length</b>	249.5	Ft	<b>From</b>	MH 14
<b>Shape</b>	Circular	<b>Size</b>	8	by	<b>To</b>	MH 13
<b>Material</b>	Polyvinyl chloride	<b>Joint spacing</b>			<b>Direction</b>	Downstream
<b>Lining</b>			<b>Year laid</b>			<b>Pre-clean</b> Y <b>Last cleaned</b> 2/1/2022
<b>General note</b>					<b>Structural</b>	<b>Service</b>
<b>Location note</b>					<b>Miscellaneous</b>	<b>Hydraulic</b>
					<b>Constructional</b>	<b>Depth</b>
						<b>Depth</b>
						<b>F</b>
						<b>t</b>
						<b>t</b>



**PipeLogix Inc.**  
**Phone: 866-299-3150**  
**Fax: 760-406-6023**

**Pipe Graphic Report of PLR**      MH 15      X      for CUMMUINTY HOA

<b>Work Order</b>	<b>Contract</b>		<b>Video</b>		<b>Setup</b>	14	
<b>Facility</b>	<b>Operator</b>	TROY	<b>Van Ref</b>		<b>Surveyed On</b>	02/03/2022	
<b>Street Name</b>	WAPITI LP & MAMITOBAN LN		<b>City</b>	HYRUM			
<b>Location type</b>							
<b>Surface</b>							
<b>Survey purpose</b>	Random survey of pipes and things		<b>Weather</b>		Snow		
<b>Pipe Use</b>	Sanitary	<b>Schedule length</b>	252.2	Ft	<b>From</b>	MH 14	
<b>Shape</b>	Circular	<b>Size</b>	8	by	ins	<b>To</b>	MH 15
<b>Material</b>	Polyvinyl chloride	<b>Joint spacing</b>			Ft	<b>Direction</b>	Upstream
<b>Lining</b>			<b>Year laid</b>			<b>Pre-clean</b>	Y
					<b>Last cleaned</b>	2/1/2022	
<b>General note</b>					<b>Structural</b>	<b>Service</b>	<b>Constructional</b>
<b>Location note</b>					<b>Miscellaneous</b>	<b>Hydraulic</b>	




**PipeLogix Inc.**  
**Phone: 866-299-3150**  
**Fax: 760-406-6023**



**Pipe Graphic Report of PLR**      MH 16      X      for CUMMUINTY HOA


<b>Work Order</b>	<b>Contract</b>		<b>Video</b>		<b>Setup</b>	13
<b>Facility</b>	<b>Operator</b>	TROY	<b>Van Ref</b>	<b>Surveyed On</b>	02/03/2022	
<b>Street Name</b>	WAPITI LP		<b>City</b>	HYRUM		
<b>Location type</b>						
<b>Surface</b>						
<b>Survey purpose</b>	Random survey of pipes and things		<b>Weather</b>	Snow		
<b>Pipe Use</b>	Sanitary	<b>Schedule length</b>	396.4 Ft	<b>From</b>	MH 16	<b>Depth</b>
<b>Shape</b>	Circular	<b>Size</b>	8 by ins	<b>To</b>	MH 15	<b>Depth</b>
<b>Material</b>	Polyvinyl chloride	<b>Joint spacing</b>	Ft	<b>Direction</b>	Downstream	
<b>Lining</b>			<b>Year laid</b>	<b>Pre-clean</b>	Y	<b>Last cleaned</b>
<b>General note</b>				Structural	Service	Constructional
<b>Location note</b>				Miscellaneous	Hydraulic	



**PipeLogix Inc.**  
**Phone: 866-299-3150**  
**Fax: 760-406-6023**

**Pipe Graphic Report of PLR**      MH 17      X      for      CUMMUINTY HOA


<b>Work Order</b>	<b>Contract</b>		<b>Video</b>		<b>Setup</b>	12
<b>Facility</b>	<b>Operator</b>	TROY	<b>Van Ref</b>	<b>Surveyed On</b>	02/03/2022	
<b>Street Name</b>	WAPITI LP		<b>City</b>	HYRUM		
<b>Location type</b>						
<b>Surface</b>						
<b>Survey purpose</b>	Random survey of pipes and things		<b>Weather</b>	Snow		
<b>Pipe Use</b>	Sanitary	<b>Schedule length</b>	122.4 Ft	<b>From</b>	MH 17	<b>Depth</b>
<b>Shape</b>	Circular	<b>Size</b>	8 by ins	<b>To</b>	MH 16	<b>Depth</b>
<b>Material</b>	Polyvinyl chloride	<b>Joint spacing</b>	Ft	<b>Direction</b>	Downstream	
<b>Lining</b>	<b>Year laid</b>			<b>Pre-clean</b>	Y	<b>Last cleaned</b>
<b>General note</b>				<b>Structural</b>	<b>Service</b>	<b>Constructional</b>
<b>Location note</b>				<b>Miscellaneous</b>	<b>Hydraulic</b>	



**PipeLogix Inc.**  
**Phone: 866-299-3150**  
**Fax: 760-406-6023**

**Pipe Graphic Report of PLR**      MH 18      X      for CUMMUINTY HOA

<b>Work Order</b>	<b>Contract</b>		<b>Video</b>		<b>Setup</b>	11
<b>Facility</b>	<b>Operator</b>	TROY	<b>Van Ref</b>		<b>Surveyed On</b>	02/03/2022
<b>Street Name</b>	WAPITI LP		<b>City</b>	HYRUM		
<b>Location type</b>						
<b>Surface</b>						
<b>Survey purpose</b>	Random survey of pipes and things		<b>Weather</b>		Snow	
<b>Pipe Use</b>	Sanitary	<b>Schedule length</b>	116.1	Ft	<b>From</b>	MH 17
<b>Shape</b>	Circular	<b>Size</b>	8	by	<b>To</b>	MH 18
<b>Material</b>	Polyvinyl chloride	<b>Joint spacing</b>			<b>Direction</b>	Upstream
<b>Lining</b>			<b>Year laid</b>			<b>Pre-clean</b> Y <b>Last cleaned</b> 2/1/2022
<b>General note</b>					<b>Structural</b>	<b>Service</b>
<b>Location note</b>					<b>Miscellaneous</b>	<b>Hydraulic</b>
					<b>Constructional</b>	



**PipeLogix Inc.**  
**Phone: 866-299-3150**  
**Fax: 760-406-6023**